## Oil Field Environmental Incident Summary

Responsible Party: Petro Harvester Operating Co

Well Operator: PETRO HARVESTER OPERATING COMPANY, LLC

Well Name: RICE-ASHIEM UTB

Field Name: RENVILLE Well File #: 0

Date Incident: 7/20/2013Time Incident: 07:45Facility ID Number: 413884-02County:RENVILLETwp: 161Rng: 82Sec: 9Qtr: SW SW

Location Description:

Submitted By: Ben Tohm Received By:

Contact Person: Ben Tohm

5160 TENNYSON PARKWAY

SUITE 3000 E PLANO, TX 75024

General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:0.5 MilesDistance Nearest Water Well:0.5 Miles

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No Spilled Units Recovered Units Followup Units

	Spilleu	Ullits	Recovered	Ullits
Oil	4	barrels	4	barrels
Brine	0	barrels	0	barrels
Other	0	barrels	0	barrels

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Fire hazard

Areal Extent:

## Potential Environmental Impacts:

## Action Taken or Planned:

Treater was taken out of service and isolated. Vac truck called out to suck up liquids, flyash applied to residuals to be placed into rolloff container for proper disposal.

Wastes Disposal Location: At approved facility

Agencies Involved: NDIC field rep

## **Updates**

Date: 7/22/2013 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release remained on location, at the treater, according to the report.